Appendix E: DERAP Wetland Assessment Stressor Checklist for Flat Wetlands in the Chester-Choptank Watershed

Stressor code descriptions are listed in Appendix B. '1' indicates stressor presence; '0' indicated stressor absence; '.' indicates the stressor category is not applicable for this HGM class. Site numbers are color-coded by condition categories (green are minimally stressed, yellow are moderately stressed, and orange are severely stressed).

Habitat and Plant Community Stressors

Site Number	QDR	Final Score	Hfor50	Hfor30	Hfor15	Hfor2	Hcc10	Hcc50	Hcc100	Hforsc	Hpine	Hchem	Hmow	Hfarm	Hgraz	Hnorecov	Hinv1	Hinv5	Hinv50	Hinv100	Hherb	Halgae	Hnis100	Hnis50	Htrail	Hroad	Hpave
CC18 1001	4	54	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1045	5	57	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1015	5	64	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	.	.	0	0	0
CC18 1057	5	64	0	0	0	0	0	0	0	1	0	0	1	0	0	0	0	1	0	0	0	0	.	.	0	0	0
CC18 1092	3	68	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	1	0	0
CC18 1014	5	68	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	0	.	.	0	1	0
CC18 1033	4	69	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1064	5	69	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	.	.	1	0	0
CC18 1059	5	70	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1090	5	70	0	0	0	0	0	0	0	1	0	0	1	0	0	0	0	0	1	0	0	0	.	.	1	0	0
CC18 1054	6	72	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	1	0	0
CC18 1024	3	72	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1093	3	76	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1021	2	77	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1067	3	79	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1008	2	79	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1042	3	79	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1046	4	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	1	0	0
CC18 1013	3	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1004	3	85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1061	2	85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1018	2	85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1084	3	86	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1034	1	86	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1066	2	89	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1041	3	89	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1002	1	92	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1055	2	92	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1091	1	92	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1085	2	92	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0

Appendix E: Continued

Stressor code descriptions are listed in Appendix B. '1' indicates stressor presence; '0' indicated stressor absence; '.' indicates the stressor category is not applicable for this HGM class. Site numbers are color-coded by condition categories (green are minimally stressed, yellow are moderately stressed, and orange are severely stressed).

Hydrology Stressors

Site Number	QDR	Final Score	Wditchs	Wditchm	Wditchx	Wchanm	Wchan1	Wchan2	Wincision	Wdamdec	Wimp10	Wimp75	Wimp100	Wstorm	Wpoint	Wsed	Wfill10	Wfill75	Wfill100	Wmic10	Wmic75	Wmic100	Wsubsid
CC18 1001	4	54	0	0	1	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1045	5	57	0	1	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1015	5	64	0	1	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1057	5	64	1	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1092	3	68	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1014	5	68	0	0	0	.	.	.	.	0	1	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1033	4	69	1	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1064	5	69	0	0	0	.	.	.	.	0	1	0	0	0	0	0	0	0	0	0	1	0	0
CC18 1059	5	70	0	0	1	.	.	.	.	0	0	0	0	0	0	0	1	0	0	0	0	0	0
CC18 1090	5	70	0	0	0	.	.	.	.	0	1	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1054	6	72	1	0	0	.	.	.	.	0	1	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1024	3	72	0	0	0	.	.	.	.	0	0	0	0	0	0	0	1	0	0	0	0	0	0
CC18 1093	3	76	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	1	0	0
CC18 1021	2	77	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1067	3	79	1	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1008	2	79	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	1	0	0
CC18 1042	3	79	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1046	4	82	0	0	0	.	.	.	.	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1013	3	82	0	1	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1004	3	85	1	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1061	2	85	0	0	0	.	.	.	.	0	0	0	0	0	0	0	1	0	0	0	0	0	0
CC18 1018	2	85	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1084	3	86	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1034	1	86	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1066	2	89	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1041	3	89	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1002	1	92	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1055	2	92	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1091	1	92	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1085	2	92	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Appendix E: Continued

Stressor code descriptions are listed in Appendix B. '1' indicates stressor presence; '0' indicated stressor absence; '.' indicates the stressor category is not applicable for this HGM class. Site numbers are color-coded by condition categories (green are minimally stressed, yellow are moderately stressed, and orange are severely stressed).

Buffer Stressors

Site Number	QDR	Final Score	Ldevcom	Ldevres3	Ldevres2	Ldevres1	Lrdgrav	Lrd2pav	Lrd4pav	Lindfil	Lchan	Lag	Lagpoul	Lfor	Lgolf	Lmow	Lmine
CC18 1001	4	54	0	0	0	1	0	0	0	0	1	0	0	0	0	1	0
CC18 1045	5	57	0	0	0	0	0	0	0	0	1	0	0	0	0	1	0
CC18 1015	5	64	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0
CC18 1057	5	64	0	0	0	0	0	0	0	0	1	0	0	0	0	1	0
CC18 1092	3	68	0	0	0	1	0	0	0	0	1	1	0	0	0	0	0
CC18 1014	5	68	0	0	0	0	1	0	0	0	0	0	0	0	0	1	0
CC18 1033	4	69	0	0	0	1	0	0	0	0	1	1	0	0	0	0	0
CC18 1064	5	69	0	0	0	0	0	0	0	0	1	0	0	1	0	0	0
CC18 1059	5	70	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0
CC18 1090	5	70	0	0	0	0	1	0	0	0	0	0	0	0	0	1	0
CC18 1054	6	72	0	0	0	1	0	0	0	0	1	1	0	0	0	1	0
CC18 1024	3	72	0	0	0	0	0	0	0	0	1	0	0	0	0	1	0
CC18 1093	3	76	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1021	2	77	0	0	0	0	0	1	0	0	0	0	0	0	0	1	0
CC18 1067	3	79	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0
CC18 1008	2	79	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1042	3	79	0	0	0	0	0	0	0	0	1	0	1	0	0	1	0
CC18 1046	4	82	0	0	0	0	1	0	0	0	1	1	0	0	0	0	0
CC18 1013	3	82	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1004	3	85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1061	2	85	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0
CC18 1018	2	85	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0
CC18 1084	3	86	0	0	0	1	0	1	0	0	0	1	0	0	0	0	0
CC18 1034	1	86	0	0	0	0	0	0	0	0	1	1	0	0	0	1	0
CC18 1066	2	89	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0
CC18 1041	3	89	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0
CC18 1002	1	92	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0
CC18 1055	2	92	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0
CC18 1091	1	92	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0
CC18 1085	2	92	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0

Appendix F: DERAP Wetland Assessment Stressor Checklist for Riverine Wetlands in the Chester-Choptank Watershed

Stressor code descriptions are listed in Appendix B. '1' indicates stressor presence; '0' indicated stressor absence; '.' indicates the stressor category is not applicable for this HGM class. Site numbers are color-coded by condition categories (green are minimally stressed, yellow are moderately stressed, and orange are severely stressed).

Habitat and Plant Community Stressors

Site Number	QDR	Final Score	Hfor50	Hfor30	Hfor15	Hfor2	Hcc10	Hcc50	Hcc100	Hforsc	Hpine	Hchem	Hmow	Hfarm	Hgraz	Hnorecov	Hinv1	Hinv5	Hinv50	Hinv100	Hherb	Halgae	Hnis100	Hnis50	Htrail	Hroad	Hpave
CC18 1080	6	39	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	1	0	0
CC18 1047	5	41	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1323	6	15	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	0	.	.	0	1	0
CC18 1515	3	54	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1419	2	84	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	.	.	0	0	0
CC18 1231	4	81	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	1	0	0
CC18 1016	3	83	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	.	.	0	0	0
CC18 1075	3	58	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1222	2	79	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1148	6	80	0	0	0	0	0	0	0	1	0	0	1	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1392	3	84	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	.	.	0	0	0
CC18 1271	3	84	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	0	0	0	0	.	.	0	0	0
CC18 1539	3	84	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1387	3	83	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	.	.	0	0	0
CC18 1011	2	85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	.	.	0	0	0
CC18 1110	2	85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	.	.	0	0	0
CC18 1186	1	90	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1331	1	90	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1087	2	90	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1508	4	88	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1144	1	86	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	.	.	0	0	0
CC18 1032	2	86	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1338	2	86	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1426	2	85	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	.	.	0	0	0
CC18 1095	2	90	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1158	1	90	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0
CC18 1534	1	90	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	.	.	0	0	0

Appendix F: Continued

Stressor code descriptions are listed in Appendix B. '1' indicates stressor presence; '0' indicated stressor absence; '.' indicates the stressor category is not applicable for this HGM class. Site numbers are color-coded by condition categories (green are minimally stressed, yellow are moderately stressed, and orange are severely stressed).

Hydrology Stressors

Site Number	QDR	Final Score	Wditchs	Wditchm	Wditchx	Wchannm	Wchan1	Wchan2	Wincision	Wdamdec	Wimp10	Wimp75	Wimp100	Wstorm	Wpoint	Wsed	Wfill10	Wfill75	Wfill100	Wmic10	Wmic75	Wmic100	Wsubsid
CC18 1080	6	39	.	.	.	0	1	0	0	0	0	0	0	0	0	0	0	1	0	1	0	0	0
CC18 1047	5	41	.	.	.	0	1	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1323	6	15	.	.	.	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0
CC18 1515	3	54	.	.	.	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1419	2	84	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1231	4	81	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1016	3	83	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1075	3	58	.	.	.	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1222	2	79	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1148	6	80	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1392	3	84	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1271	3	84	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1539	3	84	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1387	3	83	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1011	2	85	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1110	2	85	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1186	1	90	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1331	1	90	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1087	2	90	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1508	4	88	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1144	1	86	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1032	2	86	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1338	2	86	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1426	2	85	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1095	2	90	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1158	1	90	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1534	1	90	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Appendix F: Continued

Stressor code descriptions are listed in Appendix B. '1' indicates stressor presence; '0' indicated stressor absence; '.' indicates the stressor category is not applicable for this HGM class. Site numbers are color-coded by condition categories (green are minimally stressed, yellow are moderately stressed, and orange are severely stressed).

Buffer Stressors

Site Number	QDR	Final Score	Ldevcom	Ldevres3	Ldevres2	Ldevres1	Lrdgrav	Lrd2pav	Lrd4pav	Llndfil	Lchan	Lag	Lagpoul	Lfor	Lgolf	Lmow	Lmine
CC18 1080	6	39	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0
CC18 1047	5	41	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0
CC18 1323	6	15	0	0	0	1	0	1	0	1	1	0	0	0	0	1	0
CC18 1515	3	54	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1419	2	84	0	0	1	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1231	4	81	0	0	0	1	1	0	0	0	0	1	0	0	0	0	0
CC18 1016	3	83	0	0	0	1	1	0	0	0	0	1	0	0	0	0	0
CC18 1075	3	58	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0
CC18 1222	2	79	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1148	6	80	0	0	1	0	0	1	0	0	0	1	0	0	0	1	0
CC18 1392	3	84	0	0	0	1	0	0	0	0	0	0	0	0	0	1	0
CC18 1271	3	84	0	0	0	1	0	0	0	0	0	0	0	0	0	1	0
CC18 1539	3	84	0	0	0	1	0	0	0	0	0	0	0	0	0	1	0
CC18 1387	3	83	0	0	0	1	0	1	0	0	0	0	0	0	0	1	0
CC18 1011	2	85	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1110	2	85	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1186	1	90	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1331	1	90	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1087	2	90	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1508	4	88	0	0	0	1	0	1	0	0	1	1	0	0	0	0	0
CC18 1144	1	86	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1032	2	86	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1338	2	86	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1426	2	85	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0
CC18 1095	2	90	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0
CC18 1158	1	90	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0
CC18 1534	1	90	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0

Appendix G: DERAP Wetland Assessment Stressor Checklist for Depression Wetlands in the Chester-Choptank Watershed

Stressor code descriptions are listed in Appendix B. '1' indicates stressor presence; '0' indicated stressor absence; '.' indicates the stressor category is not applicable for this HGM class. Site numbers are color-coded by condition categories (green are minimally stressed, yellow are moderately stressed, and orange are severely stressed).

Habitat and Plant Community Stressors

Site Number	QDR	Final Score	Hfor50	Hfor30	Hfor15	Hfor2	Hcc10	Hcc50	Hcc100	Hforsc	Hpine	Hchem	Hmow	Hfarm	Hgraz	Hnorecov	Hinv1	Hinv5	Hinv50	Hinv100	Hherb	Halgae	Hnis100	Hnis50	Htrail	Hroad	Hpave
CC18 1039	5	19	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1	0	0	0	0	1	0	0	0
CC18 1232	3	51	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1035	2	63	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1071	3	64	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0
CC18 1312	2	74	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1135	2	74	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1099	2	74	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1131	2	74	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1270	1	78	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1287	3	78	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1168	2	78	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1292	1	78	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1299	1	78	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1366	2	80	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1019	2	82	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1275	2	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1076	1	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1408	1	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1322	1	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Appendix G: Continued

Stressor code descriptions are listed in Appendix B. '1' indicates stressor presence; '0' indicated stressor absence; '.' indicates the stressor category is not applicable for this HGM class. Site numbers are color-coded by condition categories (green are minimally stressed, yellow are moderately stressed, and orange are severely stressed).

Hydrology Stressors

Site Number	QDR	Final Score	Wditchs	Wditchm	Wditchx	Wchannm	Wchan1	Wchan2	Wincision	Wdamdec	Wimp10	Wimp75	Wimp100	Wstorm	Wpoint	Wsed	Wfill10	Wfill75	Wfill100	Wmic10	Wmic75	Wmic100	Wsubsid
CC18 1039	5	19	1	0	0	.	.	.	.	0	0	0	0	0	0	0	0	1	0	1	0	0	0
CC18 1232	3	51	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1035	2	63	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1071	3	64	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1312	2	74	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1135	2	74	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1099	2	74	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1131	2	74	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1270	1	78	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1287	3	78	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1168	2	78	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1292	1	78	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1299	1	78	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1366	2	80	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	1	0	0
CC18 1019	2	82	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1275	2	82	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1076	1	82	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1408	1	82	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1322	1	82	0	0	0	.	.	.	.	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Appendix G: Continued

Stressor code descriptions are listed in Appendix B. '1' indicates stressor presence; '0' indicated stressor absence; '.' indicates the stressor category is not applicable for this HGM class. Site numbers are color-coded by condition categories (green are minimally stressed, yellow are moderately stressed, and orange are severely stressed).

Buffer Stressors

Site Number	QDR	Final Score	Ldevcom	Ldevres3	Ldevres2	Ldevres1	Lrdgrav	Lrd2pav	Lrd4pav	Llndfil	Lchan	Lag	Lagpoul	Lfor	Lgolf	Lmow	Lmine
CC18 1039	5	19	0	0	0	0	1	0	0	0	0	1	0	0	0	0	0
CC18 1232	3	51	0	0	0	0	1	0	0	0	1	0	0	0	0	1	0
CC18 1035	2	63	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1071	3	64	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0
CC18 1312	2	74	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0
CC18 1135	2	74	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0
CC18 1099	2	74	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0
CC18 1131	2	74	0	0	0	0	0	0	0	0	0	0	0	1	0	1	0
CC18 1270	1	78	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CC18 1287	3	78	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0
CC18 1168	2	78	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0
CC18 1292	1	78	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0
CC18 1299	1	78	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0
CC18 1366	2	80	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1019	2	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1275	2	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1076	1	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1408	1	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CC18 1322	1	82	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0