BrightFields, Inc.
Environmental Evaluation Investigation, and Remediation
801 Industrial Street, Suite 1 Wilmington, Delaware 19801
302-656-9600 302-656-9700 fax

Historic Sample Locations and Aerial Photograph (2007)
Howard Street Property
Wilmington, Delaware

	By	Date	Scale:	File Name:
Drawn	SMD	9/30/08	1:300	hs aerial.mxd
Checked	JPR	9/30/08	Fig. No. Figure 1	
Project #	0985.26.51			

N:\Aerials and maps\Working GIS Files (Do Not Edit)\51 General Consulting\0985.26.51- PCB Mass Loading\Howard Street\mxds\Howard Street_aerial.mxd



Legend

- Soil Boring Location
- Soil Boring Location Where Soil Removed
- Test Pit Location
- Well Location
- Well Location Where Soil Removed
- Existing Building
- Historic Building
- Howard Street Property Boundary

Excavation Depth (feet)

- 0-0.4
- 0-1
- 0-2
- 0-3
- 0-4
- 0-5
- 0-6
- 2-4

Note: Samples in gray indicate that no sample was collected from this depth or the sample was not analayzed for PCBs.

BrightFields, Inc.
Environmental Evaluation
Investigation, and Remediation
801 Industrial Street, Suite 1
Wilmington, Delaware 19801
302-656-9600
302-656-9700 fax

PCB Distribution in Surface Soil
Howard Street Property
Wilmington, Delaware

	By	Date	Scale:	File Name:
Drawn	SMD	9/30/08	1:180	howard 0-2B.mxd
Checked	JPR	9/30/08	Fig. No.	
Project #	0885.26.51		Figure 2B	

15 7.5 0 Feet

N:\Aerials and maps\Working GIS Files (Do Not Edit)\51 General Consulting\2085.26.51- PCB Mass Loading\Howard Street\mxd\howard street 0-2 B.mxd

GLR-2
MW-9
HS-GP-1
GLR-3
GLR-1
GLR-4
HS-GP-3
HS-GP-2
CLC-23
PDWTP12
GLR-5
TT-1
(PDW) GP-16/MW-5
CLC-23
PDWTP10/14
TP-6
GLR-6
HS-GP-4
PDWTP11
CLC-22
HS-GP-4
TP-1
GLR-7
CLC-19
HS-GP-5
TP-2
TP-5
CLC-20
HS-GP-06/HS-MW-1
HS-GP-8
PDCGP1
ND
PDCGP3
ND
PDCGP9
ND
PDCGP10
ND
PDCGP4
ND
PDCGP7
ND
COW-1
GLR-8
COW-3
MARKET STREET
WALNUT STREET
HS-GP-13
GLR-9
GP-1/GW-GP-1
HS-GP-16
HS-GP-19/HS-MW-3
GP-4/GW-GP-4
HS-GP-14/HS-MW-2
GP-2/GW-GP-2
GLR-10
HS-GP-15
HS-GP-20
HS-GP-17
GP-5
HS-GP-18
GLR-11
HS-GP-21

See Figure 2C

See Figure 2B

Legend

- ND PCBs Not Detected
- Soil Boring Location
- Soil Boring Location Where Soil Removed
- Test Pit Location
- Well Location
- Well Location Where Soil Removed
- Existing Building
- Historic Building
- Tax Parcel
- Howard Street Property Boundary

Excavation Depth (feet)

- 0-0.4
- 0-1
- 0-2
- 0-3
- 0-4
- 0-5
- 0-6
- 2-4

BrightFields, Inc.
Environmental Evaluation
Investigation, and Remediation
801 Industrial Street, Suite 1
Wilmington, Delaware 19801
302-656-9600
302-656-9700 fax

PCB Distribution in Surface Soil
Howard Street Property
Wilmington, Delaware

	By	Date	Scale:	File Name:
Drawn	SMD	10/1/08	1:1050	howard 0-2 a.mxd
Checked	JPR	10/1/08	Fig. No. Figure 2A	
Project #	1106.50.52			

0 43.75 87.5 Feet

N:\Aerials and maps\Working GIS Files (Do Not Edit)\51 General Consulting\0985.26.51- PCB Mass Loading\Howard Street\mxds\howard street_0-2_a.mxd



DB3-1 DB3-2 DB3-3 DB3-4 DB3-5 DB3-6 DB3-7 DB3-8 DB3-9 DB3-10 DB3-11 DB3-12 DB3-13 DB3-13-1 DB3-14 DB3-15 DB3-16 DB3-17 DB3-18 DB3-19 DB3-20 DB3-21 DB3-22 DB3-23 DB3-24 DB3-25 DB3-26 DB3-27 DB3-28 DB3-29 DB3-30 DB3-31 DB3-32 DB3-32-2 DB3-33 DB3-33-2 DB3-34 DB3-34-2 DB3-35 DB3-35-2 DB3-36 DB3-36-2 DB3-37 DB3-37-1 DB3-38 DB3-38-1 DB3-39 DB3-39-1 DB3-40 DB3-41 DB3-41-2 DB3-42 DB3-42-1 DB3-43 DB3-44 DB3-44-2 DB3-45 DB3-45-2 DB3-46 DB3-46-2 DB3-47 DB3-47-2 DB3-48 DB3-48-2 DB3-49 DB3-49-2 DB3-50 DB3-50-2 DB3-51 DB3-51-1 DB3-52 DB3-52-1 DB3-53 DB3-53-1 DB3-54 DB3-54-2 DB3-55 DB3-55-1 DB3-56 DB3-56-1 DB3-57 DB3-57-1 DB3-58 DB3-58-1 DB3-59 DB3-59-1 DB3-60 DB3-61 DB3-62 DB3-63 DB3-63-2 DB3-64 DB3-64-2 DB3-65 DB3-66 DB3-66-1 DB3-67 DB3-68-1 DB3-69-1 DB3-70-1 DB3-71-1 DB3-72-1 DB3-73-1 DB3-74-1 DB3-75-2 DB3-76-2 PDWTP10/14 TP-1 TP-2 CLC-19

Legend

- Soil Boring Location
- Soil Boring Location Where Soil Removed
- Test Pit Location
- Debris Pile 3 Boundary
- Howard Street Property Boundary
- Excavation Areas

Note: Samples in gray indicate that no sample was collected from this depth or the sample was not analyzed for pcbs.

BrightFields, Inc.
Environmental Evaluation
Investigation, and Remediation
801 Industrial Street, Suite 1
Wilmington, Delaware 19801
302-656-9600
302-656-9700 fax

PCB Distribution in Surface Soil
Debris Pile 3
Howard Street Property
Wilmington, Delaware

	By	Date	Scale:	File Name:
Drawn	SMD	10/24/08	1:84	howard 0-2 c.mxd
Checked	JPR	10/1/08	Fig. No. Figure 2C	
Project #	1106.50.52			

0 3.5 7 Feet

N E S W

N:\Aerials and maps\Working GIS Files (Do Not Edit)\51 General Consulting\0985.26.51- PCB Mass Loading\Howard Street\mxds\howard street_0-2_c.mxd