



## State of Delaware Public Record Summary Information on Underground Storage Tanks (UST)

**Public Record Posted Date: 1/14/21**

*General Information as of 9/15/20*

**Total Number of UST Facilities subject to federal requirements: 406**

**Total Number of USTs: 1140 subject to federal requirements**

*Summary Information for On-Site Inspections*

**Number of UST Facilities Inspected (9/15/19 through 9/15/20): 118**

**Percent of facilities found to be in significant operational compliance: 94%**

**Note:** Tank, facility, and on-site inspection information is based on definitions and compliance requirements found in the DE Admin Code 1351, State of Delaware *Regulations Governing Underground Storage Tank Systems*;

*Summary of Release Sources and Causes for the time period 9/15/19 through 9/15/20*

**Number of Confirmed Releases during the time period 9/15/19 through 9/15/20: 20**

Source (% is based on the total number of releases with known sources)			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	5	33	0	0	0	0	0	0	1	20	0	0	0	0	4	80
Piping	3	20	0	0	0	0	1	33	0	0	0	0	0	0	2	67
Dispenser	3	20	0	0	0	0	0	0	0	0	0	0	1	33	2	67
Turbine Pump (STP)	1	7	0	0	0	0	0	0	0	0	0	0	0	0	1	100
Fill Port Spill Bucket	1	7	0	0	0	0	0	0	0	0	0	0	0	0	1	100
Vapor Recovery Containment	1	7	0	0	0	0	0	0	0	0	0	0	0	0	1	100
Vent/Vapor Line	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Other	1	7	0	0	0	0	0	0	0	0	0	0	0	0	1	100
Unknown	8															
<b>Total number of releases with known sources (% of known)</b>	<b>15</b>	<b>101</b>	<b>0</b>	<b>0%</b>	<b>0</b>	<b>0%</b>	<b>1</b>	<b>7%</b>	<b>1</b>	<b>7%</b>	<b>0</b>	<b>0%</b>	<b>1</b>	<b>7%</b>	<b>12</b>	<b>80%</b>

Notes: 1) Release, source and cause information is based on data collected by State of Delaware employees and are identified through field observation and confirmed with soil testing when retrofit, repair, tank removal, or hydrogeological investigation activities are conducted. 2) A Confirmed Release may have more than one Source. Therefore, the tabulated number of Sources (known and unknown) exceeds the Number of Confirmed Releases. 3) To obtain facility specific information please use our environmental navigator system found at: <http://www.nav.dnrec.delaware.gov/DEN3/> or call 302-395-2500.